

TEMPERATURE DETECTOR

UNLOADING TEMPERATURE DETECTOR GEVA Mod. RT200

Temperature detector GEVA RT600 detect hot pieces with a temperature more than 200°C.



Fig.1 Side view of the temperature detector RT200

When hot pieces pass in front of the detector, the detector send an impulse to the plc and the automation could unload the piece from the press.



Fig.2 Rear view of the temperature detector RT600

In the rear of the detector there is two leds with a different color:

- 1) **First LED – red color:** the detector has power supply.
- 2) **Second LED – green color:** piece are detected and with right temperature (>200°C.)

Differently from loading temperature detector mod. RT600 there is no potentiometer to regulate the sensibility.